National Transportation Safety Board
PRELIMINARY REPORT
AVIATION

NTSB ID: ERA13LA183 Most Critical Injury: Fatal

Occurrence Date: 03/29/2013 Investigated By: NTSB

Location/Time

Nearest City/PlaceStateZip CodeLocal TimeTime ZoneCollegedaleTN373021530EDT

Occurrence Type: Accident

Aircraft Information

Registration Number Aircraft Manufacturer Model/Series Number

N999NA Andrews Zodiac/601XL

71101010

Type of Aircraft: Airplane

Amateur Built Aircraft? Yes

Injury Summary:

Fatal

1

Serious

Minor

None

1

Revenue Sightseeing Flight: No Air Medical Transport Flight: No

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

\*\*\* Note: NTSB investigators may not have traveled in support of this investigation and used data provided by various sources to prepare this aircraft accident report. \*\*\*

On March 29, 2013, about 1530 eastern daylight time, an experimental amateur-built Zodiac 601XL, N999NA, operated by a private individual, sustained minor damage during an in-flight upset near Collegedale Municipal Airport (FGU), Collegedale, Tennessee. The flight instructor was not injured and the private pilot was fatally injured. The instructional flight was conducted under the provisions of 14 Code of Federal Regulations Part 91. Visual meteorological conditions prevailed and no flight plan was filed for the local flight that departed FGU about 1510.

According to the flight instructor's written statement, the private pilot purchased the airplane about 3 weeks before the accident and was not familiar with it. The flight instructor agreed to provide instruction in the airplane and first wanted familiarize himself with it. The flight instructor flew the airplane solo uneventfully on two occasions, for a total of approximately 2 hours, with the second flight ending just before the accident flight began. After his second solo flight, the flight instructor shut down the engine and reviewed the airplane's characteristics with the private pilot. They then returned to the airplane, took their time entering the cockpit, fastened their seatbelts and secured the canopy; however, they were unable to start the engine.

The private pilot subsequently unlatched and raised the canopy to call for assistance from ground personnel. A ground person provided a charger for the airplane's battery. As he started to attach the charger, the private pilot unbuckled his seatbelt to assist; however, the ground person stated that the private pilot did not need to get out of the airplane as he did not require any help. The private pilot then put his seatbelt back on, more hastily than the first time, and appeared to fasten it again. The flight instructor thought he heard a "click," but could not see the private pilot's seatbelt with the center console between them. The pilots lowered the canopy and latched it a second time for the planned 20-minute flight.

About 5 minutes into the flight, the flight instructor heard a wind noise from behind their heads, which he did not hear on previous flights and thought that perhaps the canopy did not have a perfect seal to the fuselage. As the flight progressed, the canopy seemed like it may have separated a little more. By that time, the flight was headed back to the airport. The canopy then pulled up enough on the latches that the flight instructor could see daylight through the openings between the canopy and fuselage. The flight instructor attempted to pull the canopy down, but it instead opened completely and the airplane entered a negative g dive. He was not sure if the change in airflow or a control input by the private pilot caused the dive. The private pilot lifted out of his seat and ejected out of the cockpit. The flight instructor was able to grab the control stick, arrest the dive, and land back at FGU uneventfully. Emergency responders later recovered the private pilot in a wooded area.

National Transportation Safety Board
PRELIMINARY REPORT
AVIATION

NTSB ID: ERA13LA183

Occurrence Date: 03/29/2013

Occurrence Type: Accident

Narrative (	(Continu	ied)
I Tallative	COLLUITO	-

Examination	ı of	the airg	plane by	a Fed	eral	Aviatio	on Adı	ministratio	n inspe	ctor rev	ealed mi	inor da	amage to
the fusela	ıge.	Initial e	examinat	ion of	the	canopy	and	the private	e pilot'	s seatbe	lt did r	not rev	<i>r</i> eal any
failures.	The	inspecto	or was	able	to	secure	and	release	both th	e canopy	and sea	atbelt	without
difficulty.													

Updated on Apr 4 2013 9:29AM

TRANSO
National Transportation Safety Board
PRELIMINARY REPORT
ÁVIATION

NTSB ID: ERA13LA183

PRELIMINARY REPORT AVIATION			Occurrence Date: 03/29/2013									
			Occurren	се Туре:	Accio	dent						
Other A	ircraft Involved		•									
Registration	on Number		Model/Series Number									
Accident Information												
Aircraft D	amage: Minor			Accid	lent C	occurred Durin	ng:					
Crew	N	ame				Certificate No.				Injury		
Pilot	On File				Or	n File		١	lone			
2	On File				Or	n File		F	atal			
3												
4												
5												
6												
	or Information											
Name David T	Richardson	Desig	esignator Code Doing Business As									
Street Address City Cha											Zip Code 37421	
-Type of Certificate(s) Held: None												
Air Carrie	er Operating Certificate(	s):										
Operatino	g Certificate:	0	Operator Certificate:									
Regulatio	n Flight Conducted Und	ler: Part 91: Gener	ral Aviation	1								
Type of FI	ight Operations Conduc	ted: Instructional										
Flight P	lan/Itinerary											
Type of F	Flight Plan Filed: None								_			
Last De	parture Point		State Airport Identifier									
Same as Accident/Incident Location								U				
Destination						State		dentifier				
Local Flight						TN	FGU					
Weathe	r Information											
Investigat	or's Source: Unknown	Facil	Facility ID: CHA Ob			Observation Time (Local): 1553						
Sky/Lowest Cloud Condition: Ft. AGL												
Lowest Ceiling: Broken 10000 Ft. AGL						isibility:	10	SM	Altim	neter:		"Hg
		PRELIMINARY	INFORM	ATION -	SUE	ВЈЕСТ ТО С	CHANC	GE	-			Page 2

## National Transportation Safety Board

NTSB ID: ERA13LA183

PRELIMINARY REPORT		Occ	urrence D	ate: 03/29/2013					
AVIAT	ION		Occ	urrence T	ype: Accident				
Weather Information		(Continued from page	e 2)						
Temperature:	°C	Dew Point:	°C	Wind D	virection: 360				
Wind Speed: 8	Kts	. Gusts:	Kts.	Weather Conditions at Accident Site: Visual Conditions					
Administration Data									
Notification From					Date				
FAA Southern ROC									
FAA District Office/Coordin			Investigator-In-Charge (IIC)						
FAA/FSDO Pamela K. Charles					Robert J. Gretz				
			·	·					