RICKEY TICEY

FIXED NUMEROUS HOLES IN WALLS AND REMOVED ALL GRAFFITTI ON ALL HALLWAYS, LOBBIES, WOOD PART OF SOFAS, INSIDE ROOMS, BATHROOMS, ETC. BY SANDING AND CAULKING

REPAIRED TERMITE DAMAGED CLOSETS (4) — REBUILT TO ACCOMMODATE CLOTHING SPACE FOR TWO STUDENTS

REPAIRED (REPLACING WITH GRAPHITE) COUNTER TOPS IN 25 ROOMS – OTHERS TO BE DONE AT A LATER DATE – BECAUSE OF CIGARETTE BURNS (BADLY DISFIGURED) DESKTOPS, DRESSERSREBUILT ROOM 222 ON FISCHER AND STEVENS HALL – THESE ROOMS WERE NOT USED AT ALL – USED FOR STORAGE –THE ROOMS ARE NOW RENTED TO STUDENTS – WE HAVE NO STORAGE ROOMS

103 – STEVENS – THIS WAS THE ROOM – NOW CALLED THE (HONORS SUITE) – WAS BOLTED UP WITH STORAGE OF A REFRIGERATOR (FULL SIZED), COOKSTOVES (2) MATTRESSES, ETC. – ROOM RENOVATED AND REPAIRED AND HOLES FIXED, MILDEW REMOVED, CABINETS PUT IN, ETC, NOW IT IS THE ROOM WHERE TWO STUDENTS RESIDE – TWO STUDENTS WITH 4.0 GPA'S FROM HIGH SCHOOL – THE ROOM CONTAINS—REFRIGERATOR, TELEVISION, COMPUTER, PRINTER, LAB TOP, CEILING FAN, LIGHT FIXTURES, TOWELS, IRON, PICTURES, ETC.

103 – JOHNSON – THIS WAS THE ROOM – NOW CALLED THE (HONORS SUITE)
BOYS SIDE – WAS BOLTED UP – NOT USABLE – NOW TWO STUDENTS WITH 4.01
GPA'S FROM HIGH SCHOOL – THE ROOM CONTAINS – REFRIGERATOR,
TELEVISION, COMPUTER, PRINTER, LAPTOP, CEILING FAN, LIGHT FIXTURES,
TOWELS, PICTURES, ETC.

FIXED NUMEROUS DRAWERS THAT NEEDED REPAIR FROM MOISTURE – MOST DRAWERS WHEN OPENED WOULD FALL APART – MANY REPAIRED BY SOMEONE ELSE HAD TO BE REDONE AS THEY WERE NAILED TOGETHER AND MANY HAD NAILS VISIBLY ON THE OUTSIDE OF THE DRAWERS WHICH WOULD CAUSE THE STUDENTS TO INJURE THEMSELVES

PUT KNOBS ON EACH DRAWER ON STEVENS HALL – 1^{ST} , 2^{ND} , AND 3^{RD} FLOORS (10 KNOBS IN EACH ROOM)

PUT HANDLES ON EACH DOOR – OUTSIDE DOORS OF EACH ROOM ON STEVENS HALL

SPRAYED THE ENTIRE DORM – FISCHER/STEVENS – JOHNSON/COPELAND – 260 ROOMS (1^{ST} , 2^{ND} , 3^{RD} FLOORS OF EACH HALL) ONCE A WEEK UNTIL ONE WEEK PRIOR TO THE STUDENTS RETURN TO RID THE DORM OF SPIDERS (PLENTIFUL), WATERBUGS, OTHER CRAWLING INSECTS

HUNG ALL PICTURES ON THE HONORS HALL AND FISCHER, COPELAND, AND JOHNSON

REPAIRED ALL TABLES AND STOOLS AND POOL TABLE (1) – TABLES AND STOOLS ARE REPAIRED EACH SUMMER – WE HAVE NOT PURCHASED ADDITIONAL TABLES OR STOOLS BECAUSE OF THE UPKEEP AND REPAIR THAT IS DONE AFTER EACH HAS BEEN DAMAGED - DRAWERS ARE ALSO REPAIRED AS THEY ARE BROKEN CONTINUOUSLY THROUGHOUT THE YEAR

COMPLETE UPKEEP OF THE ENTIRE GROUNDS CONTINUOUSLY

REPAIRED LAWN MOWER, REPLACED BELTS ON RIDING MOWER, REPAIRED WEEDEATER, REPLACED WEEDEATER CABLES

EACH TIME ELECTRICITY WOULD GO OFF, MR. TICEY WOULD COME OUT AND "TRIP THE BREAKERS" ON EACH HALL – TOTAL 12 HALLS WITH KNOWLEDGE OF WHERE EACH BREAKER IS

ADJUST UNITS IN ROOMS EACH TIME BREAKERS ARE OFF – HEATERS OR AIR GOES OFF















